

























Woodbridge Town Council Asset Report


Location	WTC Asset No	Asset Name	Category	Site Specific Location	Condition	Comments	Date of Inspection	Picture
<u>Elmhurst Park</u>								
	69	Bollard	Structures	Bollard in Elmhurst Walk	Good		29-May-19	
	70	Gate	Gates/Railings	Entrance from Elmhurst Walk	Good	Will soon need repainting - some mold/lichen coming through.	29-May-19	
	71	Sign	Signs/Boards	Sign on gate from Elmhurst Walk	Good		29-May-19	
	73	Bench	Seat/Bench	Located along from the Dell	Bad	The bench requires restaining and the legs painting with Hammerite.	29-May-19	
	74	Bench	Seat/Bench	Located close to Holm Oak	Bad	The bench requires cleaning and restaining.	29-May-19	
	75	Litter bin	Litter Bin	Near Bench Asset WTC 73	Good		29-May-19	





<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	76	Bench	Seat/Bench	Located close to Holm Oak	Bad	The bench requires restaining and the legs painting with Hammerite.	29-May-19	
	77	Bench	Seat/Bench	Located close to Holm Oak	Bad	The bench requires restaining.	29-May-19	
	78	Litter bin	Litter Bin	Near Holm Oak	Good	New bin - New photo needed.	29-May-19	
	79	Bench	Seat/Bench	located around Holm Oak - opposite play area	Good		29-May-19	
	85	Public toilet	Land and Buildings		Good	Suffer from periodic vandalism.	29-May-19	
	90	Litter bin	Litter Bin	Located opposite to play area	Good		29-May-19	
	91	Boaty McBoatface	Play and Sports Equi	Play area	Good		29-May-19	




<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	92	Munchy the Caterpillar seat	Seat/Bench	Play area	Good		29-May-19	
	93	Blue bench	Seat/Bench	Play area	Bad	Needs repainting - Amenities Committee agreed that the handyman can undertake this work; will be done summer 2019.	29-May-19	
	94	Cradle seat swings	Play and Sports Equi	Play area	Good		29-May-19	
	96	Litter bin	Litter Bin	Rear of Play area	Good		29-May-19	
	97	Flat seat swings	Play and Sports Equi	Play area	Good	Two swings	29-May-19	
	100	Springy animal rocker (horse)	Play and Sports Equi	Play area	Good		29-May-19	
	101	Springy animal rocker (duck)	Play and Sports Equi	Play area	Good	Unknown	29-May-19	








<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	102	Blue bench	Seat/Bench	near the play area	Bad	Needs repainting - Amenities Committee agreed that the handyman can undertake this work; will be done summer 2019.	29-May-19	
	103	Mini roundabout	Play and Sports Equi	Play area	Good	Known as a Spica	29-May-19	
	104	Bench	Seat/Bench	near play area	Good	Suffers regular vandalism - recently repaired by the handyman (May '19)	29-May-19	
	105	Main gates to Elmhurst Park	Gates/Railings	Main gates from Quayside	Good		29-May-19	
	107	Litter bin	Litter Bin	Near main gates on Quay Side	Good		29-May-19	
	108	Fido Bin	Fido Bin	Near to gates on Quay Side	Good	Old Style bin - photo correct - possibly replace with a new bin?	29-May-19	








<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	109	Bench	Seat/Bench	Near to gates on Quay Side	Bad	The bench requires restaining and the legs painting with Hammerite.	29-May-19	
	110	Bench	Seat/Bench	Near to gates on Quay Side FACING Quayside	Bad	The bench requires restaining and the legs painting with Hammerite.	29-May-19	
	111	Bench	Seat/Bench	Lower Path	Bad		29-May-19	
	112	Bench plaque	Bench Plaque	on bench no: 111	Good		29-May-19	
	113	Bench	Seat/Bench	Lower Path FACING Quayside	Bad	The bench requires restaining and the legs painting with Hammerite.	29-May-19	
	114	Litter bin	Litter Bin	Enter park from Quay Side turn right on lower path	Good		29-May-19	

<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	115	Bench	Seat/Bench	Enter park from Quay Side turn right on lower path	Bad	The bench requires restaining and the legs painting with Hammerite.	29-May-19	
	116	Sundial	Structures	Close to gates near workshop	Bad	Looking tired - Could do with a rub down/ re- paint. Potentially no longer 'working'.	29-May-19	
	117	Litter bin	Litter Bin	Close to gates near workshop	Good		29-May-19	
	118	Gates	Gates/Railings	Lime Kiln Quay entrance	Good		29-May-19	
	123	Bench	Seat/Bench	Scouts Corner	Bad	The bench requires restaining.	29-May-19	
	124	Bench plaque	Bench Plaque	Scouts Corner on bench no: 123	Good		29-May-19	







Location	WTC Asset No	Asset Name	Category	Site Specific Location	Condition	Comments	Date of Inspection	Picture
	125	Bench	Seat/Bench	Scouts Corner	Bad	The bench requires restaining.	29-May-19	
	126	Bench plaque	Bench Plaque	Scouts Corner on bench no: 125	Good		29-May-19	
	127	Bench	Seat/Bench	Scouts Corner	Bad	The bench requires restaining.	29-May-19	
	128	Bench plaque	Bench Plaque	Scouts Corner on bench 127	Good		29-May-19	
	129	Bench	Seat/Bench	On circular route from Quay Side gates to Elmhurst cottage	Bad	The bench requires restaining and the legs painting with Hammerite.	29-May-19	
	130	Bench	Seat/Bench	On circular route from Quay Side gates to Elmhurst Cottage	Bad	The bench requires restaining.	29-May-19	







<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	131	Bench Plaque	Bench Plaque	On circular route from Quay Side gates to Elmhurst Cottage on bench: 130	Good		29-May-19	
	132	Bench	Seat/Bench	On circular route from Quay Side gates to Elmhurst cottage	Bad	The bench requires restaining and the legs painting with Hammerite.	29-May-19	
	133	Bench	Seat/Bench	Near Entrance from Gardeners Shed	Good		29-May-19	
	134	Bench plaque	Bench Plaque	On bench no: 133	Good		29-May-19	
	135	Litter bin	Litter Bin	Close to shelter	Good		29-May-19	
	136	Shelter	Structures		Good	Some broken tiles and graffiti. Repainted and minor repairs undertaken in spring '19.	29-May-19	





<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	141	Litter bin	Litter Bin	Near to shelter	Good		29-May-19	
	142	Bench	Seat/Bench	Close to shelter	Bad	The bench requires restaining.	29-May-19	
	143	Plaque	Bench Plaque	situated on bench no: 142	Good		29-May-19	
	144	Bench	Seat/Bench	Close to shelter	Bad	The bench requires restaining.	29-May-19	
	145	Bench plaque	Bench Plaque	Situated on bench no: 144	Good		29-May-19	
	146	Bench	Seat/Bench	Close to shelter	Bad	The bench requires restaining.	29-May-19	
	147	Bench plaque	Bench Plaque	situated on bench no: 146	Good		29-May-19	

<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	148	Bench	Seat/Bench	Close to bowling green and shelter	Bad	The bench requires restaining.	29-May-19	
	149	Bench plaque	Bench Plaque	located on WTC asset 148	Good		29-May-19	
	150	Bench	Seat/Bench	close to bowling green and shelter	Bad	The bench requires restaining.	29-May-19	
	151	Flagpole	Structures		Good		29-May-19	
	153	Sundial	Structures		Good		29-May-19	
	154	Sundail	Structures		Good		29-May-19	
	155	Fido Bin	Fido Bin	near to sundial	Good	Old style of bin - photo is correct. Possibly replace with newer model.	29-May-19	

<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	156	Park gates	Gates/Railings	Near bowling green	Good		29-May-19	
	158	Workshop noticeboard	Signs/Boards	Workshop Walls	Bad	Wooden frame needs fixing or even replacing. Currently on handyman's list.	29-May-19	
	159	Workshop	Land and Buildings	workshop	Good	Main doors could do with being replaced.	29-May-19	
	172	Bollards	Structures	near to Lime Kiln Quay road	Good		29-May-19	
	175	Cannon	Structures	Junction of Lime Kiln Quay Road	Bad	Could do with restoration - wheels are broken, plaque is hidden - Currently being restored (May 19)	29-May-19	
	176	Bandstand	Structures		Good	21ft Ollerton Imperial Bandstand - Currently missing Crown.	29-May-19	

Location	WTC Asset No	Asset Name	Category	Site Specific Location	Condition	Comments	Date of Inspection	Picture
	449	Pergola	Structures	Scouts Corner over Bench WTC Asset No125	Good		29-May-19	
	450	Bench	Seat Bench	near Holm Oak	Bad	The bench requires restaining and the legs painting with Hammerite.	29-May-19	
	451	Litter Bin	Litter Bin	near Holm Oak	Good		29-May-19	
	452	Litter Bin	Litter Bin	Adjacent to Toilet Block	Good		29-May-19	
	453	Bench	Seat/Bench	Adjacent to Copper Beach	Good	Gerry & Joan Cooper Woodbridge Community Council 2015	29-May-19	
	454	Plaque	Tree Plaque	Adjacent Elmhurst Court Border	Good	Donated by Ye Old Belle & Steelyard Monday Club	29-May-19	

<i>Location</i>	<i>WTC Asset No</i>	<i>Asset Name</i>	<i>Category</i>	<i>Site Specific Location</i>	<i>Condition</i>	<i>Comments</i>	<i>Date of Inspection</i>	<i>Picture</i>
	455	Sign	Signs/Boards	Attached to fence in supermarket car park	Bad	Bad condition - paint peeling off and boards coming apart.	29-May-19	
	457	Sign	Signs/Boards	Entrance to park from Elmhurst Walk	Good		29-May-19	
	468	Sign	Signs/Boards	Off Lime Kiln Quay Road	Good	x 2 signs	29-May-19	
	478	Bandstand Electricity Cupboard	Structures	Adjacent to the bandstand	Good		29-May-19	
	479	Sign	Signs/Boards	Next to the sundial flowerbed	Good		29-May-19	
	480	Sign	Signs/Boards	Next to the flowerbed close to large sundial	Good		29-May-19	

Location	WTC Asset No	Asset Name	Category	Site Specific Location	Condition	Comments	Date of Inspection	Picture
	481	Sign	Signs/Boards	In the flower adjacent to the main entrance (Quayside)	Good		29-May-19	
	482	Bench	Seat/Bench	On the circular route from Quay Side gates to Elmhurst Cottages	Good		29-May-19	
	533	Metal Surface Mounted Protective Meter Box	Structures	Fixed to the back wall of the toilet block over the original protective box.	Good		29-May-19	
	542	Close gate behind you sign	Signs/Boards	Main gates to Station Road/ Lime Kiln Quay.	Good	Signs purchased from Amazon, £4.79 each.	29-May-19	
	560	Bird Bath	Structures	Island bed close to the bandstand.	Good		29-May-19	